

This LightWELD_1000 folder is for updating software for
LightWELD® **1000** welders only.

LightWELD® 1000 welders use SWFP0000**86**XXXXU Software Suite.

Do not update a LightWELD® 1500 or LightWELD 1500XC® or
LightWELD® 1500XR welder, or LightWELD_2000XR® with this code- it
will cause the welder to operate incorrectly due to hardware
differences in the products. There is a different folder for LightWELD®
1500 or LightWELD 1500XC®, LightWELD® 1500XR, and LightWELD®
2000XR models.

Similarly, do not load code intended for LightWELD®1500 or
LightWELD® 1500XC or LightWELD® 1500XR or LightWELD®2000XR
models into LightWELD® 1000XR models. It will cause the welder to
operate incorrectly due to hardware differences in the products.

LightWELD® 1500 and **LightWELD® 1500XC** welders use
SWFP0000**14**XXXXU Software Suite.

LightWELD® 1500XR welders use SWFP0000**40**XXXXU Software Suite.

LightWELD® 2000XR welders use SWFP0000**67**XXXXU Software Suite.