

This LightWELD_2k folder is for updating software for
LightWELD® **2000XR** welders only.

LightWELD® 2000XR welders use SWFP0000**67**XXXXU Software Suite.

Do not update a LightWELD® 1500 or LightWELD 1500XC® or
LightWELD® 1500XR welder with this code- it will cause the welder to
operate incorrectly due to hardware differences in the products. There
is a different BOX folder for LightWELD® 1500 or LightWELD 1500XC®
and LightWELD® 1500XR models.

Similarly, do not load code intended for LightWELD® 1500 or
LightWELD® 1500XC or LightWELD® 1500XR models into LightWELD®
2000XR models. It will cause the welder to operate incorrectly due to
hardware differences in the products.

LightWELD® 1500 and **LightWELD® 1500XC** welders use
SWFP0000**14**XXXXU Software Suite.

LightWELD® 1500XR welders use SWFP0000**40**XXXXU Software Suite.