

ReleaseNotes

fpga-image-1.5-r70514

- MOF reset bug
- Latching of Command and Fifo Overrun Errors

fpga-image-1.5-r69586

- Support for Extended I/O Box
- Fiber Interlock Reporting
- External Controller Synchronization
- 3D Head Breaks Fiber Interlock if Guide is in Beam
- Latches Command Error and disables laser until reset

fpga-image-1.5-r62854

- Fix Reset of Encoder Home Position Sensors
- Add Servo Error Status to Warning Messages

fpga-image-1.5-r55139

- Improved photo-detector read timing for weld monitoring.
- SW settable Error Indicator