ReadMe

 $laser\text{-}user\text{-}3.5\text{-}r8813.cortexa9hf_neon.rpm$

• Fixes issue with setting fixedIP address for controller through ScannerUtility